


BUILDING STYLE	1. Conv. 2. Bl Level 3. Split Lev. 4. Contemp.	5. Log 6. Earth Berm 7. Seasonal 8. Other	S/F BSMT LIVING	FIN BSMT GRADE	LAYOUT	1. Typical 2. Inadeq.
OTHER UNITS						
STORIES	1. One 2. Two 3. Three	4. 1 1/2 5. 1 3/4 6. 2 1/2				
EXTERIOR WALLS	1. Wood 2. Al/Inyl 3. Comp. 4. Asb/Asp.	5. Stucco 6. Mas. Ven. 7. Masonry 8. Other				
ROOF SURFACE	1. Asphalt 2. Slate 3. Metal	4. Comp. 5. Wood 6. Other				
S/F MASONRY TRIM						
YEAR BUILT		1967				
YEAR REMODELED						
FOUNDATION	1. Conc. 2. C. Blk. 3. Br/Stone	4. Wood 5. Slab 6. Piers				
BASEMENT	1. 1/4 2. 1/2 3. 3/4	4. Full 5. Crawl 9. None				
BSMT GAR # CARS						
WET BASEMENT	1. Dry 2. Damp	3. Wet 9. None				
S O F T W A R E Practical Computer Solutions C O R P O R A T I O N						
ADDITIONS, OUTBUILDINGS & IMPROVEMENTS						
TYPE	YEAR	UNITS	GRADE	COND.	PERCENT GOOD	
					Pvts.	Funct.
23	1970	576	31.00	4	100	100
24	1985	128	11.00	4	100	100
25	1992	440	31.00	4	100	100
26	1992	343	31.00	4	100	100
27	1992	258	21.00	4	100	100
28	1995	258	21.00	4	100	100

ATTIC	1. Full Stairs 2. 1/4 Fin. 3. 1/2 Fin. 9. None	4. 3/4 Fin. 5. Full Fin. 6. 1/2 Fin. 9. None	INSULATION	1. Full 2. Capped 3. Minimal 9. None	UNFINISHED %	GRADE & FACTOR	1. E 2. D 3. C 4. B	5. B+ 6. A 7. A+ 8. AA	SO. FOOTAGE	CONDITION	1. Poor 2. Fair 3. Avg. 4. Avg.	5. Avg. + 6. Good 7. V. Good 8. Exc.	PHYS. % GOOD	FUNCT. % GOOD	FUNCT. CODE	1. Incomp. 2. Overall 9. None	ECON. % GOOD	ECON. CODE	1. Location 2. Entrance 3. Services 9. None	ENTRANCE CODE	1. Inspect 2. Refused 3. Tenant 4. Estimate	INFO. CODE	1. Owner 2. Relative 3. Tenant 4. Agent 5. Estimate 6. Other	DATE INSP.	

24 HESHLAND AVE



1. 19 Ft  
2. 25 Ft  
3. 35 Ft  
4. 11/25 Ft  
5. 13/45 Ft  
6. 21/25 Ft

- 21. OPP
- 22. EPP
- 23. Garage
- 24. Sheel
- 25. Bay Window
- 26. Overhang
- 27. Unl. Bent
- 28. Unl. Attic
- 29. Fin. Attic
- Add 20 for 2 Story
- 61. Canopy
- 62. Swimming Pool
- 63. Tennis Court
- 64. Barn
- 65. Solar Room
- 66. Natatorium
- 67. Wood Deck
- 68. Hot Tub
- 69. Sauna